

District **Kandhamal** Block **Phiringia** Village **Banduli**  
 School Name **Banduli PUPS** School Code **21210807201**  
 No. of Student **119** Girls- **53** Boys- **66**  
 Status of toilet Existing - **1 (fully damaged)** Not Existing  
 Toilet Requirement Girls Boys - **1**

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		
2	Urinals		
3	Doors (size)		
4	Floor level		
5	Wall level		
6	Internal plaster		
7	Outer plaster		
8	Inspection Chamber		
9	Lease pit / septic tank		

Source of Water Bore well with pump / Hand  pump  
 Water tank **NIL** Ground / Overhead  
 Water tank Capacity

Remarks if any: - Sufficient water is not available from hand pump.  
 - No electricity connection  
 - Existing toilet is fully damaged & not in usable condition.  
 - One toilet block is under construction.

**Narayan**  
 Sign of School head master  
 Head master  
 U.P School Banduli

Sign of School Mgt Committee

Sign of Surveyor

Name **Narayan Nayak**  
**8895337852**

Name **Prasanna Didi**

Name

**Robith MR**

**Robith MR**