165

Round seal and HM seal not available

CRC Co-ordinator 9/3/15
Amurutulu Cluster
Surada Block (Gm)

"स्वच्छ भारत अभियान"

DISTRICT: Ganjam BLOCK: Surada VILLAGE: Srirampalli

SCHOOL NAME: Srirampalli P.S. SCHOOL CODE: 21192218901

NO. OF STUDENT: 42 GIRLS: 20 BOYS: 22

STATUS OF TOILET: EXISTING: ✓ (Damaged) NOT EXISTING:

TOILET REQUIREMENT: GIRLS: 1 WC + 1 Urinal BOYS: 1 WC + 1 Urinal

If EXISTING:

Sl.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC		1 (Badly damaged)
2	URINALS		1
3	DOORS(SIZE)		✓
4	FLOOR LEVEL		✓
5	WALL LEVEL		✓
6	INTERNAL PLASTER		✓
7	OUTER PLASTER		✓
8	INSPECTION CHAMBER		✓
9	LEASE PIT/ SEPTIC TANK		✓

SOURCE OF WATER: BORE WELL WITH PUMP: ✗ HAND PUMP: 1 (dysfunctional)

WATER TANK: ✗ GROUND: ✗ OVERHEAD:

WATER TANK CAPACITY:

Remarks If any: – No electricity
– No water supply (needed urgently)
– No boundary wall (Boundary Wall Required)

HM on leave
Incharge
4/3/15
ASHUTOSH SAHOO
9861607304

Sign of School Head Master | Sign of School Mgt Committee | Sign of Surveyor 4/2/15

NAME: | NAME: ASHUTOSH SAHOO (Member) | NAME: Swyat Kumar Dash