

District *Kandhamal* Block *Phiringia* Village *Bandhagarh.*
 School Name *Bandhagarh P.S* School Code *21210801801*
 No. of Student *136* Girls- *93* Boys- *43*
 Status of toilet Existing *01 WC for girls* Not Existing
 " " " *boys*
 Toilet Requirement Girls *01 for Handicap* Boys
 If Existing: *01 set*

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	<i>03</i>	
2	Urinals		
3	Doors (size)	<i>0.75 x 2.00</i>	
4	Floor level	<i>0.25</i>	
5	Wall level	<i>2.10</i>	
6	Internal plaster	<input checked="" type="checkbox"/>	
7	Outer plaster	<input checked="" type="checkbox"/>	
8	Inspection Chamber	<input checked="" type="checkbox"/>	
9	Lease pit / septic tank	<input checked="" type="checkbox"/>	

Source of Water Bore well with pump / Hand pump
 Water tank Ground / Overhead (not functioning)
 Water tank Capacity

Remarks if any: *No electricity*

Prakash Chandra Mahapatra
 Sign of School head master
8895/20103

Satish Kumar Nayak
 Sign of School Mgt Committee
8895/22051

Asstn
 Sign of Surveyor

Name

Name

John Bachra
 Name

Handwritten signature