


64

Sno - 535 / 64



BHANDARIJHARA P.P.S

"स्वच्छ भारत अभियान"

SCHOOL NAME: BHANDARIJHARA PRJ. P.S.

VILLAGE: Samanbhuin

SCHOOL CODE: 1014501

NO. OF STUDENT: 33

GIRLS: 17

BOYS: 16

STATUS OF TOILET:

EXISTING: ✓ (needs urgent repair)

NOT EXISTING:

TOILET REQUIREMENT:

GIRLS: 01

BOYS: 01

IF EXISTING: 2 urinals (B, G) and 1 WC → to be repaired (major water problem)

nearby RWSS pipeline available

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	✓	02
2	URINALS	✓	02
3	DOORS(SIZE)	✓	/
4	FLOOR LEVEL	✓	
5	WALL LEVEL	✓	
6	INTERNAL PLASTER	✓	
7	OUTER PLASTER	✓	
8	INSPECTION CHAMBER		
9	LEASE PIT/ SEPTIC TANK	damaged and choked	✓

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: 2

WATER TANK:

GROUND: X

OVERHEAD: (dysfunctional) X

WATER TANK CAPACITY:

Remarks If any:

- no electricity supply  
- major water deficiency (as the 2 handpumps have become dysfunctional)

S. Routaray  
29.01.015  
Sign of School Head Master  
D. 29.01.015

Sign of School Mgt Committee

Swagat Das  
29/01/15  
Sign of Surveyor  
MT (EW)

NAME: SARBESWAR ROUTARAY

NAME: CHANDEGWAR BHOLA

NAME: SWAGAT DAS

M- 9937323240

Headmaster

Bhandarijhar Project P.S. School  
Tangi, Khordha

Chairperson S. M. C.  
Bhandarijhar Project P.S. School  
Tangi, Khordha