

1638

District Bolarni Block Titlagarh Village Bijepur
 School Name Govt. U.P. School Bijepur School Code 1638 21241303/02
 No. of Student 138 Girls- 65 Boys- 73
 Status of toilet Existing Not Existing
 Toilet Requirement Girls Boys

If Existing:


| Sl.No | Item | Condition | |
|-------|-------------------------|--------------------|--|
| | | Good in Nos. | To be replaced in Nos. |
| 1 | WC | 4 (2) | X 2 |
| 2 | Urinals | 4 (2) | X 2 |
| 3 | Doors (size) | X | <input checked="" type="checkbox"/> (2) |
| 4 | Floor level | X I.P.S | X <input checked="" type="checkbox"/> |
| 5 | Wall level | B/W (0.25) | X <input checked="" type="checkbox"/> |
| 6 | Internal plaster | 4 | X <input checked="" type="checkbox"/> |
| 7 | Outer plaster | 4 | X <input checked="" type="checkbox"/> |
| 8 | Inspection Chamber | X | X <input checked="" type="checkbox"/> |
| 9 | Lease pit / septic tank | 4 | X <input checked="" type="checkbox"/> |

Source of Water Bore well with pump / Hand pump
 Water tank Ground / Overhead
 Water tank Capacity
 Electricity - Available / Not available.

Remarks if any: Boys toilet is damaged & girls toilet is under construction.


 Headmaster
 Sign of School head master
 Govt. U. P. School
 Bijepur


 Sign of School Mgt Committee


 Sign of Surveyor

Name

Name

Name C. K. Patel

