


Name - P/Head master - TILOTTAMA BADHIA (H/C) . Mobil No - 9438611109



KALAHANDI Block BHAWANI PATNA Village WARD - 14 (New No. 18)  
 Karapita P.S. School Code 21261401402

No. of Student 76 Girls- 37 Boys- 39  
 Status of toilet Existing B-1 w/c 0 Not Existing -  
 Girls HC-1 X Boys 7

Toilet Requirement Girls 1 X Boys 1 X  
 If Existing: 1 (one)

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	2	
2	Urinals	3	
3	Doors (size)	5, 2 <sup>nd</sup> 20.60	
4	Floor level	✓ Tilt	
5	Wall level	✓ Tilt	
6	Internal plaster	✓	
7	Outer plaster	✓	
8	Inspection Chamber	✓	
9	Lease pit / septic tank	✓	

Source of Water - Bore well with pump / Hand pump - 1 (one)

Water tank YES Ground X / Overhead - 1 (one) dysfunction

Water tank Capacity 500 Lt

- Damaged school building needs urgent attention.

Remarks if any: - No electricity

- Existing toilet are in good condition

Tilottama Badhia.  
 Sign of School head master  
 HEADMASTER

Prakash Ghosh  
 Sign of School Mgt Committee  
 CHAIRMAN C.M.C.

Vinay Kumar  
 Sign of Supervisor 15/02/15

Karapita P.R.Y. School

Karapita P.R.Y. School

Name TILOTTAMA BADHIA Name TRIMAN GHAI

Name VINAY KUMAR