

Bwla NAC Hand no. 14

District SAMBALPUR Block DHANKODA Village KIRBA

School Name KIRBA P School Code 1001106

No. of Student 157 Girls- 91 Boys- 66

Status of toilet Existing (under const.) Not Existing

Toilet Requirement Girls 2 Boys 2

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	<u>NIL</u>	
2	Urinals		<input checked="" type="checkbox"/>
3	Doors (size)		<input checked="" type="checkbox"/>
4	Floor level		<input checked="" type="checkbox"/>
5	Wall level		<input checked="" type="checkbox"/>
6	Internal plaster		<input checked="" type="checkbox"/>
7	Outer plaster		<input checked="" type="checkbox"/>
8	Inspection Chamber	<u>NIL</u>	
9	Lease pit / septic tank	<u>NIL</u>	

Source of Water Bore well with pump / Hand pump

Water tank Ground NIL / Overhead NIL

Water tank Capacity

Remarks if any:

Existing toilets are in bad condition and need to be replaced. There is no water tank in the school.

Sign of School head master

Sign of School Mgt Committee

Arabinda Saha
Sign of Surveyor

Panchali Panda
Name

Name ଅରବିନ୍ଦ ସାହୁ

ARABINDA SAHOO
Name

Conr. - 9861427525

8/1/15