

District: KANDHAMAL

Block: PHULBANI

Village: DUDUKI GP

Schools Name: Kusumbata PS

School Code: 21210905901

No. of students: 16 Boys: 07 Girls: 09

Status of Toilets: Exists/ Non-Exists No. of Boys Toilet: No. of Girls Toilet: CWSN: 03

No. of Toilets Required: Boys: 01 Girls: NA

Specification of Toilets:

Sl No.	Items	Goods in Nos.	Specification of Goods	Replaceable in nos.	Remarks
01	WC Commode	03	Commod = 01 W-C = 02		W-C = 01 fully damaged.
02	Urinals	02	Boys: 01 Girls: 01		fully damaged
03	Doors		Type: Steel/ PVC/ Wood Size:		
04	Flooring		Tiles: <input checked="" type="checkbox"/> Concrete: <input checked="" type="checkbox"/>		old of toilet with urinal fully damaged.
05	Wall Level Flooring		Height: 2 1/2 Tile: <input checked="" type="checkbox"/> Concrete: <input checked="" type="checkbox"/>		do -
06	Internal Plaster		CP: <input checked="" type="checkbox"/> Other:		
07	External Plaster		CP: <input checked="" type="checkbox"/> Other:		
08	Inspection Camber		Exists: Not-Exists: <input checked="" type="checkbox"/>		
9	Lease Pit/Septic Tank		Exists: <input checked="" type="checkbox"/> Not-Exists:		
10	Electricity		Available: Not-Available:		
11	Drainage System		Available: Not Available: <input checked="" type="checkbox"/>		

Sources of Water: Well/Well with pump/Bore well with pump/Hand pump or Tube well

Water Tank: NA Concrete/PVC Overhead/Underground Tank Water Capacity:

Remarks or Suggestions if any:

one boys toilet required.

Suresh chandra Biswal

Sig. of School HM



Sig. of SMC

LTI of Hanabati Digal

B. Bahoo

Sig. of TC



Sig. of Surveyor

Name:

Mb. No.:

8895119777

Headmaster
Kusumbata Primary Sch

Name:

Mb. No.:

Chairman
Kusumbata Primary School

Name: Gurnaya Bhoi

Technical Consultant

Phulbani Block
RTE-550, Kandhamal