

1461


District BOLANGIR Block SAINTALA Village Badamunda
 School Name BADAMUNDA GOVT PRIMARY SCHOOL School Code 21241201101
 No. of Student 32 Girls 16 Boys 16
 Status of toilet Existing Not Existing
 Toilet Requirement Girls Boys

If Existing:


Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	4	1
2	Urinals	4	2
3	Doors (size)	X	✓
4	Floor level	X	✓
5	Wall level	X	✓
6	Internal plaster	X	✓
7	Outer plaster	X	✓
8	Inspection Chamber	X	✓
9	Lease pit / septic tank	X	✓

Source of Water Bore well with pump / Hand pump
 Water tank Ground / Overhead
 Water tank Capacity
 Electricity - Available / Not available.

Remarks if any: 1/2 Damaged Boys toilet


 Sign of School Headmaster
 Badamunda Govt. Pri. School
 SAINTALA, BOLA
 Name Lalit Patel


 Chairman / member
 Govt. Primary School
 Badmunda
 Sign of School Mgt Committee
 Name Lalit Patel


 Sign of Surveyor
 Name Sumantra Kumar Patel


 08/11/15