

1558

District BOLANGIR Block SAINTALA Village GURUMANI
 School Name GURUMANI VPS School Code 21241210102
 No. of Student 14 Girls 6 Boys 8
 Status of toilet Existing Not Existing
 Toilet Requirement Girls X Boys ✓

If Existing:

| Sl.No | Item | Condition | |
|-------|-------------------------|--------------|------------------------|
| | | Good in Nos. | To be replaced in Nos. |
| 1 | WC | <u>X</u> | <u>✓ 2</u> |
| 2 | Urinals | <u>X</u> | <u>✓ 2</u> |
| 3 | Doors (size) | <u>X</u> | <u>✓</u> |
| 4 | Floor level | <u>X</u> | <u>✓</u> |
| 5 | Wall level | <u>X</u> | <u>✓</u> |
| 6 | Internal plaster | <u>X</u> | <u>✓</u> |
| 7 | Outer plaster | <u>X</u> | <u>✓</u> |
| 8 | Inspection Chamber | <u>X</u> | <u>✓</u> |
| 9 | Lease pit / septic tank | <u>X</u> | <u>✓</u> |

Source of Water Bore well with pump / Hand pump
 Water tank X Ground / Overhead
 Water tank Capacity X
 Electricity - Available / Not available.

Remarks if any: There is NO toilet in this school.
Storeroom NO available.

Bijay Baban Bunde
Sign of School head master

[Signature]
Sign of School Mgt Committee

[Signature]
Sign of Surveyor

Name

Name

Name Sumanta Kumar Patel

[Signature]
08/11/15