

School started in 2010, but school building still under-constructed and no toilet infra. exists



179

"स्वच्छ भारत अभियान"

DISTRICT: Ganjam

BLOCK: Surada

VILLAGE: Santinagar

SCHOOL NAME:

SANTINAGAR N.P.5

SCHOOL CODE: 21192223801

NO. OF STUDENT: 51

GIRLS: 29

BOYS: 22

STATUS OF TOILET:

EXISTING: X

NOT EXISTING: ✓

TOILET REQUIREMENT:

GIRLS: (1+1)

BOYS: (1+1)

IF EXISTING:

no toilet infra. exists

8 (h)

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC		
2	URINALS		
3	DOORS(SIZE)		
4	FLOOR LEVEL		
5	WALL LEVEL		
6	INTERNAL PLASTER		
7	OUTER PLASTER		
8	INSPECTION CHAMBER		
9	LEASE PIT/ SEPTIC TANK		

SOURCE OF WATER:

BORE WELL WITH PUMP: 01

HAND PUMP: X

WATER TANK:

GROUND: X

(throughout the year)

OVERHEAD: X

WATER TANK CAPACITY:

Remarks If any:

- no electricity supply
- only source of water (1 tubewell)

Kailash Mohan

Sign of School Head Master

04.03.2015

NAME:

Kailash Mohan

रामा माहिक

Sign of School Mgt Committee

NAME:

RAMA MAHIK

Swagat Das

Sign of Surveyor

4/3/15
MT(En)

NAME: SWAGAT

DAS

8895586663

9778883557

Headmaster

Govt. Santinagar P.S
Surada Block