

Sambalpur MPL

Ward no. 20 (10)

District Sambalpur Block ~~Dhananjaya~~ Village ~~Badabazar~~

School Name Badabazar Boys UPS School Code 21031402001

No. of Student 30 Girls- Boys- 30

Status of toilet Existing Not Existing

Toilet Requirement Girls Boys 1

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	<input checked="" type="checkbox"/>	
2	Urinals	NIL	
3	Doors (size)	<input checked="" type="checkbox"/>	
4	Floor level	<input checked="" type="checkbox"/>	
5	Wall level	<input checked="" type="checkbox"/>	
6	Internal plaster	<input checked="" type="checkbox"/>	
7	Outer plaster	<input checked="" type="checkbox"/>	
8	Inspection Chamber	NIL	
9	Lease pit / septic tank	<input checked="" type="checkbox"/>	

Source of Water Bore well with pump / Hand pump PHED

Water tank NIL Ground / Overhead

Water tank Capacity

Remarks if any:

one boys toilet is urgently require in the school. There is no water supply to the existing toilets.

Sign of School head master

Sign of School Mgt Committee

Sign of Surveyor

D. K. Das
16-1-15
Name
HEADMASTER

Sabita Banerjee
Name
CHAIRMAN

A. Sahoo
16.1.2015
Name

BADABAZAR BOYS U.P. SCHOOL
SAMBALPUR

SCHOOL MANAGEMENT COMMITTEE
BADABAZAR BOYS U.P. SCHOOL
SAMBALPUR

9437882649