

1647

District Bolanis Block Dihagan Village Thubudins  
 School Name Govt. P.V.P. School Thubudins School Code 1647 21241303901  
 No. of Student 114 Girls 51 Boys 63  
 Status of toilet Existing  Not Existing  
 Toilet Requirement Girls  Boys

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	4 <del>5</del>	<del>1</del> 1
2	Urinals	4	<del>2</del> 2
3	Doors (size)	0.62 X 1.78 X 2 1.85 X 0.40 X 1	<del>1</del> 1
4	Floor level	1.P.S.	<del>1</del> 1
5	Wall level	B/W 0.25	<del>1</del> 1
6	Internal plaster	4	<del>1</del> 1
7	Outer plaster	4	<del>1</del> 1
8	Inspection Chamber	X	<del>1</del> 1
9	Lease pit / septic tank	4	<del>1</del> 1

Source of Water  Bore well with pump /  Hand pump  
 Water tank  Ground /  Overhead  
 Water tank Capacity   
 Electricity  Available /  Not available.

Remarks if any: Boys toilet is Damage 2 girls toilet is under construction.

Hari Shankar Nay  
 Sign of School head master  
 Govt. P.U.P. School  
 Thubuding  
 Name

Jitendra Patel  
 Sign of School Mgt Committee  
 Chairman SMC  
 Govt. P.U.P.S. Thubuding  
 Name

S.K. Patel  
 Sign of Surveyor  
 Name S.K. Patel

S.K. Patel  
08/11/15