

01

03  
03-03-15

District **Ganjam** Block **Buajuda** Village **Adipur**  
 School Name **Adipur PUPS** School Code **21190502A01**  
 No. of Student Girls **147** Boys **143**  
 Status of toilet Existing **01 (Girls)** None Existing  
 Toilet Requirement Girls **0** Boys **01**

If Existing:

Sl. No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		1 nos
2	Urinals		<del>3 nos</del> - Nil -
3	Doors (size)		2 x 0.70 x 1.85
4	Floor level		<del>1.80</del> 0.300
5	Wall level		2.00
6	Internal plaster		- Bad
7	Outer plaster		Beed
8	Inspection Chamber		-
9	Lease pit / septic tank		1 nos -

Source of Water Bore well with pump / Hand pump  (Not working in summer season)  
 Water tank Ground / Overhead  
 Water tank Capacity

Remarks if any: **Girls toilet needs repair work. One toilet for boys is required.**

Sign of School head master  
**HEADMASTER**  
**Project U.P. School**  
**Adipur, Ganjam**

Sign of School Mgt Committee

Sign of Surveyor

Name **Rajkishor Dash** Name

9438277319  
 Name **S.K. Padhi**

9861771818

*Handwritten signature*

20  
3/3/15