

02

04
03-03-15

District Ganjam Block Budauda Village Adipur
 School Name Baradipalli P.S. School Code 21190502402
 No. of Student Girls- 21 Boys- 22
 Status of toilet Existing 02 (Boys and girls) Note Existing
 Toilet Requirement Girls 0 Boys 0

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		1 nos -
2	Urinals		3 nos -
3	Doors (size)		4 x 0.70 x 1.60
4	Floor level		0.300
5	Wall level		1.90
6	Internal plaster		Bad
7	Outer plaster		Bad
8	Inspection Chamber		-
9	Lease pit / septic tank		-

Source of Water Bore well with pump / Hand pump
 Water tank Ground / Overhead
 Water tank Capacity

Remarks if any: Girls ~~Boys~~ toilets needs repairing work. As the existing boys toilet is deplacated, hence one toilet for boys required.

Suresh
3.3.15
Sign of School head master

Sign of School Mgt Committee

Shy
03-03-15
Sign of Surveyor

Headmaster
Primary School
Baradipalli (Gm)
Name S. Sora Kumar Dash

Name

9438277319
Name S. K. Pathe

9937051242

Suresh
3/3/15

Shy
3/3/15