

District BOLANGIR Block BALANGIR Village RANAKHOL
 School Name RANAKHOL Grant P.S. School Code 21240204002
 No. of Student 25 Girls- 08 Boys- 17
 Status of toilet Existing Not Existing
 Toilet Requirement Girls 01 Boys 01

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		
2	Urinals		
3	Doors (size)		
4	Floor level		
5	Wall level		
6	Internal plaster		
7	Outer plaster		
8	Inspection Chamber		
9	Lease pit / septic tank		

Source of Water Bore well with pump / Hand pump
 Water tank Ground / Overhead
 Water tank Capacity

Remarks if any: Toilet existing but not functional. Required construction of new toilet.

[Signature]
 Sign of School head master

Not Available
 Sign of School Mgt Committee

[Signature]
 Sign of Surveyor

BIJAY PRASAD MISHRA
 Name

Name

SUNNY RAJ, PAPPU KR. BARIK
 Name

[Signature]
 8/8/15