

12-02-2015

3

District Tajpur Block Bodaehana Village Baidehipur
 School Name Baidehipur PS School Code 21130116601
 No. of Student Girls- 15 Boys- 24
 Status of toilet Existing IN Not Existing
 Toilet Requirement Girls 01 Boys 01

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC		1 No
2	Urinals	—	—
3	Doors (size)	1.64 x 0.70	
4	Floor level	0.20	
5	Wall level	1.80	
6	Internal plaster		To be repair
7	Outer plaster		To be repair
8	Inspection Chamber		3 Nos.
9	Lease pit / septic tank	—	—

Source of Water Bore well with pump / Hand pump (Not working)
 Water tank Ground — / Overhead —
 Water tank Capacity N/A

Remarks if any: As there is no urinal and hence both toilets for boys and girls are required.

[Signature]
Sign of School head master

Sign of School Mgt Committee

[Signature]
Sign of Surveyor

Name Madan Mohan Mondal Name
 I.C. Field Officer
Block - Pr. School 8895610700

Name So mya Ranjan Singh

[Signature]
05/11/15