

5

13-02-2015

District Jajpur Block Badaehana Village Gargalli
 School Name Malika Suni Bidyapitha School Code 21130117602
 No. of Student Girls- 114 Boys- 154
 Status of toilet Existing 02 Not Existing
 Toilet Requirement Girls - Boys 01

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	1 No + 1 No	
2	Urinals	2 Nos (B)	
3	Doors (size)	2x 1.70 x 0.68 1.70 x 0.60	1.70 x 0.68
4	Floor level	0.20, 0.15	
5	Wall level	1.85, 1.75	
6	Internal plaster		To be repair
7	Outer plaster	Good	
8	Inspection Chamber	-	-
9	Lease pit / septic tank	1 No	-

Source of Water

Bore well with pump /

Hand pump

Water tank

Ground - /

Overhead -

Water tank Capacity

Remarks if any:

Boys toilet is in good condition.
 Girls toilet is required.



Sign of School Headmaster

Sign of School Mgt Committee



Sign of Surveyor

Name Dr Sudhakar Ch Samal NameName Soumya Ranjan SahaCell No - 9438300379
