

8

13-02-2015

District **Jajpur** Block **Badachana** Village **Bhakuda**
 School Name **Bhakuda Nodal VPS** School Code **21130118301**
 No. of Student Girls- **64** Boys- **80**
 status of toilet Existing **03** Date Existing **up**
 Toilet Requirement Girls **-** Boys **01**

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	1 No + 1 No + 1 No	
2	Urinals	1 No (0)	
3	Doors (size)	2x 1.65x x 0.60	
4	Floor level	0.30	
5	Wall level	1.85, 1.90	
6	Internal plaster	Good	
7	Outer plaster	Good	
8	Inspection Chamber	1 No	
9	Lease pit / septic tank		

Source of Water Bore well with pump / Hand pump
 Water tank Ground / Overhead
 Water tank Capacity **N/A**

Remarks if any: **Boys toilet is in good conditions - Girls toilet is required.**

Sas
 13.02.15
 Sign of School head master

Sign of School Mgt Committee

Sonye
 Sign of Surveyor

Bhakuda Headmaster
 Name **Santi lata Das**
 9937718553

Name

Name

Sonye
 Sign

N/A
 05/11/15