

20

13-02-2015

OB

District Tajpur Block Badachana Village Makundapur
 School Name Makundapur PS School Code 21138118601
 No. of Student Girls - 11 Boys - 7
 Status of toilet Existing 02 Not Existing
 Toilet Requirement Girls Boys 01

If Existing:

Sl.No	Item	Condition	
		Good in Nos.	To be replaced in Nos.
1	WC	1 NO	1 NO
2	Urinals.	—	—
3	Doors (size)	1.72 X 0.87	
4	Floor level	0	
5	Wall level	1.80	
6	Internal plaster	Good	
7	Outer plaster	Good	
8	Inspection Chamber	1 NO	
9	Lease pit / septic tank	—	—

Source of Water Bore well with pump / Hand pump

Water tank Ground / Overhead —

Water tank Capacity

Remarks if any:

As there is no urinal and brace both
toilets for boys and girls are required.

Dhrebanandatarr
Sign of School head master
Headmaster
Makundapur P.Ry. School

Sign of School Mgt Committee

Singh
Sign of Surveyor

Name 9438681150

Name

Name Sange Ray Singh
S.S. Singh

11/2/2015