

269

22/1/15

**“स्वच्छ भारत अभियान”**

DISTRICT: KHORDHA

BLOCK: BEGUNIA

VILLAGE: BASUDEVPUR

SCHOOL NAME: BASUDEVPUR PS

SCHOOL CODE: 21170408501

NO. OF STUDENT: 44

GIRLS: 19

BOYS: 25

STATUS OF TOILET:

EXISTING: ✓

NOT EXISTING: —

TOILET REQUIREMENT:

GIRLS: 1

BOYS: X

IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	2 Nos. (1 western 1 Indian)	—
2	URINALS	—	—
3	DOORS(SIZE)	✓	—
4	FLOOR LEVEL	✓	—
5	WALL LEVEL	✓	—
6	INTERNAL PLASTER	✓	—
7	OUTER PLASTER	✓	—
8	INSPECTION CHAMBER	X	—
9	LEASE PIT/ SEPTIC TANK ✓	✓	—

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: ✓

WATER TANK:

GROUND: X

OVERHEAD: X

WATER TANK CAPACITY: X

Remarks If any:

- \* overhead tank with water supply required
- \* urinals need to be constructed separately.
- \* No electricity supply in school premises.

Nalini Prava Devi  
Sign of School Head Master

Basudevpur Primary School  
O. M. Hivedar  
NAME: Nalini Prava Devi

22-1-15

Kunjabihan Mahapatra  
Sign of School Mgt Committee  
CHAIRPERSON

S.M.C. Basudevaur Primary School  
NAME: Kunjabihan

mahapatra

22/1/15

Sign of Surveyor

NAME: Anu K. Sariswal  
22/1/15