

273

22/1/15

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA

BLOCK: BEGUNIA

VILLAGE: BEGUNIA

SCHOOL NAME: BEGUNIA CPS

SCHOOL CODE: 21170401301

NO. OF STUDENT: 96

GIRLS: 50

BOYS: 46

STATUS OF TOILET:

EXISTING: X

NOT EXISTING: ✓

TOILET REQUIREMENT:

GIRLS: 1

BOYS: 1

If EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	X	✓
2	URINALS	X	✓
3	DOORS(SIZE)	X	✓
4	FLOOR LEVEL	X	✓
5	WALL LEVEL	X	✓
6	INTERNAL PLASTER	X	✓
7	OUTER PLASTER	X	✓
8	INSPECTION CHAMBER	X	✓
9	LEASE PIT/ SEPTIC TANK	X	✓

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: ✓ 2 in Nos

WATER TANK: X

GROUND: X

OVERHEAD: X

WATER TANK CAPACITY:

Remarks If any: * New construction with water supply required

R. Devi dt. 22.1.15
Sign of School Head Master
Headmaster

Center Primary School

NAME: Rencubala Devi

Sarbeswar Sahoo
Sign of School Mgt Committee

Chairperson

School Managing Committee

NAME: Center Primary School

Sign of Surveyor

NAME: P. V. Paul

Ann le. Parshad