

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA BLOCK: BEGUNIA VILLAGE: BADA TULASIPUR
 SCHOOL NAME: BHAGABATI GIRLS HS, TULASIPUR SCHOOL CODE: 21170 411501
 NO. OF STUDENT: 193 GIRLS: 193 BOYS: X
 STATUS OF TOILET: EXISTING: ✓ NOT EXISTING: -
 TOILET REQUIREMENT: GIRLS: - BOYS: -
 If EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	2 in No.	-
2	URINALS	3 in No.	Roof needs to be built.
3	DOORS(SIZE)	✓	-
4	FLOOR LEVEL	✓	-
5	WALL LEVEL	✓	-
6	INTERNAL PLASTER	✓	-
7	OUTER PLASTER	✓	-
8	INSPECTION CHAMBER	X	-
9	LEASE PIT/ SEPTIC TANK	✓	new septic tank for ^{urinal} required

SOURCE OF WATER: WELL BORE WELL WITH PUMP: X HAND PUMP: X

WATER TANK: GROUND: X OVERHEAD: ✓

WATER TANK CAPACITY: 1500 Ltr.

Remarks if any: * New septic tank for urinal required.
 * Overhead tank with roof required
 * Overhead tank exists but in school premises.

23.1.15
 Sign of School Head Master
 Headmistress
 Bhagabati Girl's High School
 Tulasipur, Khordha
 NAME: Narasingh Nayak

23.1.15
 Sign of School Mgt. Committee
 CHAIRMAN S. M.C.
 BHAGABATI GIRL'S HIGH SCHOOL
 AT/PO TULASIPUR, DIST. KHORDHA
 NAME: Somnath Sahu
 23.1.15

23/1/15
 Sign of Surveyor
 NAME: P. U. Parwal
 Anur K. Parwal