

282

23/1/15

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA

BLOCK: BEGUNIA

VILLAGE: CHIRAMARU

SCHOOL NAME: CHIRAMARU P U P S

SCHOOL CODE: 21170410801

NO. OF STUDENT: 98

GIRLS: 48

BOYS: 50

STATUS OF TOILET:

EXISTING: ✓

NOT EXISTING: —

TOILET REQUIREMENT:

GIRLS: 1

BOYS: 1

If EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	—	—
2	URINALS	—	—
3	DOORS(SIZE)	—	—
4	FLOOR LEVEL	—	—
5	WALL LEVEL	—	—
6	INTERNAL PLASTER	—	—
7	OUTER PLASTER	—	—
8	INSPECTION CHAMBER	—	—
9	LEASE PIT/ SEPTIC TANK	—	—

SOURCE OF WATER:

BORE WELL WITH PUMP: ✗

HAND PUMP: ✓

WATER TANK:

GROUND: ✗

OVERHEAD: ✗

WATER TANK CAPACITY:

Remarks if any: ✗ Existing toilet fully damaged.

✗ New toilets and urinals need to be constructed with all facilities.

Gobinda chandra senapati
Sign of School Head Master
23/1/2015

Renuka Manikya
Sign of School Mgt Committee
23-1-2015

Sign of Surveyor

NAME: Nile Provar
23/1/15

NAME: Anuric Parawal

NAME:

HEADMASTER

Chiramaru Project U.P. School
PO-Bhogada, Dist-Khordha

NAME:

Chairman S.M.C
Chiramaru P.U.P School
Khurda