

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA

BLOCK: BEGUNIA

VILLAGE: CHUTIPALANGA

SCHOOL NAME: CHOTIPALANGA PS

SCHOOL CODE: 21170404301

NO. OF STUDENT: 64

GIRLS: 43

BOYS: 21

STATUS OF TOILET:

EXISTING:

NOT EXISTING:

TOILET REQUIREMENT:

GIRLS: ✓

BOYS: ✗

IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	1	to be repaired
2	URINALS	2	-
3	DOORS(SIZE)	✓	-
4	FLOOR LEVEL	✓	Need to be repaired
5	WALL LEVEL	✓	
6	INTERNAL PLASTER	✓	Need to be repaired
7	OUTER PLASTER	✓	Need to be repaired
8	INSPECTION CHAMBER	✗	
9	LEASE PIT/ SEPTIC TANK	✓	Need to be repaired

SOURCE OF WATER:

BORE WELL WITH PUMP: ✗

HAND PUMP: ✓

WATER TANK:

GROUND: ✗

OVERHEAD: ✗

WATER TANK CAPACITY:

Remarks If any: ✗ Overhead tank with water supply to the toilets required
 ✗ Girls toilet needs to be built with full facilities.
 ✗ No electricity in premises.

T. Mahapatra
 Sign of School Head Master
 HEADMASTER

Sign of School Mgt Committee

Sign of Surveyor

Chotipalang Primary School

ଶ୍ରୀ ମତ୍ତ ଶ୍ରୀ ଶ୍ରୀ

24/1/15

NAME: Telottama Mahapatra

NAME:

NAME: P. U. P. S. ...

Amu ...