



334

23/1/15

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA

BLOCK: BEGUNIA

VILLAGE: PANGARSINGH

SCHOOL NAME: DADHIBAMAN DEV HS

SCHOOL CODE: 21170411301

NO. OF STUDENT: 150

GIRLS: 60

BOYS: 90

STATUS OF TOILET:

EXISTING:

NOT EXISTING:

TOILET REQUIREMENT:

GIRLS: 1

BOYS: X

IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	2 in NO.	-
2	URINALS	2 in NOS	Roof required
3	DOORS(SIZE)	✓	2 doors of size 6'x2' to be replaced.
4	FLOOR LEVEL	✓	-
5	WALL LEVEL	✓	-
6	INTERNAL PLASTER	✓	-
7	OUTER PLASTER	✓	-
8	INSPECTION CHAMBER	X	-
9	LEASE PIT/ SEPTIC TANK	✓	Required to be repaired

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: (Not working properly)

WATER TANK:

GROUND: X

OVERHEAD:

WATER TANK CAPACITY: 1000 Ltr.

Remarks if any: *

- Pipeline exists but no water supply
- Overhead tank with water supply required
- One overhead tank exists in premises, water supply from village water
- Power supply exists

Sign of School Head Master

Sign of School Mgt Committee

Sign of Surveyor

NAME:

NAME:

NAME:

BABULI DAS
HEADMASTER

Pijush Bidi

Arjun K. Panigrahi

DADHIBAMAN DEV HIGH SCHOOL
PANGARSINGH, KHORDHA

23/01/2015

Rina Das (बिंदु देवी)