

284

25/1/15

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA

BLOCK: BEGUNIA

VILLAGE: DALAKA

SCHOOL NAME: DALAK UG MES

SCHOOL CODE: 21170403201

NO. OF STUDENT: 146

GIRLS: 76

BOYS: 70

STATUS OF TOILET:

EXISTING: ✓

NOT EXISTING: —

TOILET REQUIREMENT:

GIRLS: 1

BOYS: 1

IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	1 NO	Need to be replaced
2	URINALS	2 NO	Need to be repaired
3	DOORS(SIZE)	✓	—
4	FLOOR LEVEL	✓	Flooring need
5	WALL LEVEL	✓	—
6	INTERNAL PLASTER	✓	—
7	OUTER PLASTER	✓	—
8	INSPECTION CHAMBER	X	—
9	LEASE PIT/ SEPTIC TANK	X	—

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: 2 (1 Not working)

WATER TANK:

GROUND: X

OVERHEAD: X

WATER TANK CAPACITY:

Remarks If any: \* Overhead tank with water supply to the toilets required.  
\* Septic tank required

Sign of School Head Master

Sign of School Mgt Committee

Sign of Surveyor

*Bisramji Narayan Parikya*  
NAME: *Bisramji Narayan Parikya*  
Dalak U.G.M.E. School  
DIST. KHURDA

NAME:

NO- S.M.C.  
*Oriz*

NAME:

*Pr. U. P. S. W. D.*  
Aom le. Sais wal