

47 985

25/1/15

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA

BLOCK: BEGUNIA

VILLAGE: DALATOLA

SCHOOL NAME: DALATOLA NODAL UPS

SCHOOL CODE: 2170409702

NO. OF STUDENT: 270

GIRLS: 123

BOYS: 147

STATUS OF TOILET:

EXISTING: ✓

NOT EXISTING: —

TOILET REQUIREMENT:

GIRLS: —

BOYS: 1

If EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	—	—
2	URINALS	—	—
3	DOORS(SIZE)	—	—
4	FLOOR LEVEL	—	—
5	WALL LEVEL	—	—
6	INTERNAL PLASTER	—	—
7	OUTER PLASTER	—	—
8	INSPECTION CHAMBER	—	—
9	LEASE PIT/ SEPTIC TANK	—	—

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: ✓

WATER TANK:

GROUND: X

OVERHEAD: X

WATER TANK CAPACITY:

Remarks if any: * Existing toilet fully damaged.

* New construction with all facilities required.

Patra

Sign of School Head Master

Sign of School Mgt Committee

Brajabandhu Mohapatra
NAME:

Jayanta School.
NAME:

Sign of Surveyor

Patra
25/1/15

NAME: P. K. Patra
Arun C. Jaiswal