

287

25/11/15

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA

BLOCK: BEAUNIA

VILLAGE: DEULI

SCHOOL NAME: DEULI PS

SCHOOL CODE: 2117 0403 401

NO. OF STUDENT: 93

GIRLS: 44

BOYS: 49

STATUS OF TOILET:

EXISTING: ✓

NOT EXISTING: —

TOILET REQUIREMENT:

GIRLS: 1

BOYS: 1

IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	X	1 to be replaced
2	URINALS	X	<
3	DOORS(SIZE)	✓	—
4	FLOOR LEVEL	✓	Flooring Needs to be done
5	WALL LEVEL	✓	—
6	INTERNAL PLASTER	✓	—
7	OUTER PLASTER	X	—
8	INSPECTION CHAMBER	X	—
9	LEASE PIT/ SEPTIC TANK	✓	Damaged, Not in use

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: ✓

WATER TANK:

GROUND: X

OVERHEAD: ✓

WATER TANK CAPACITY: 700 ltr. approx

Remarks if any: * urinals need to be newly constructed
* water supply from overhead tank to be given to toilets

M. Deee

Sign of School Head Master

NAME: M. Deee
ବିଦ୍ୟାଳୟ ମୁଖ୍ୟ
ନାମ: ମେ. ଡି. ଡି. ଡି.

R.K. Biswal

Sign of School Mgt Committee

NAME: R.K. Biswal
CHAIRPERSON
Deuli Primary School

Signature

Sign of Surveyor

NAME: P. K. P. P. P.
25/11/15

NAME: P. K. P. P. P.
Arun Kumar Das