

## "स्वच्छ भारत अभियान"

DISTRICT: KHORDHA

BLOCK: BEGUNIA

VILLAGE: DINGARA

SCHOOL NAME: DINGAR HS

SCHOOL CODE: 21170404401

NO. OF STUDENT: 314

GIRLS: 165

BOYS: 149

STATUS OF TOILET:

EXISTING: ✓

NOT EXISTING: —

TOILET REQUIREMENT:

GIRLS: 2

BOYS: 2

IF EXISTING:

| SI.NO. | ITEM                   | CONDITION    |   |
|--------|------------------------|--------------|---|
|        |                        | GOOD IN NOS. | TO BE REPLACED IN NOS.                                |
| 1      | WC                     | 2 m' No's    | —   |
| 2      | URINALS                | 2 m' No's    | Needs Repairing                                       |
| 3      | DOORS(SIZE)            | —            | 3 m' No's small Unit size Needs to be changed 6'x2.5' |
| 4      | FLOOR LEVEL            | ✓            | Needs Repairing                                       |
| 5      | WALL LEVEL             | X            |   |
| 6      | INTERNAL PLASTER       | ✓            |   |
| 7      | OUTER PLASTER          | X            | Needs Plastering                                      |
| 8      | INSPECTION CHAMBER     | X            |   |
| 9      | LEASE PIT/ SEPTIC TANK | ✓            | Damaged   |

SOURCE OF WATER:

BORE WELL WITH PUMP: ✓

HAND PUMP: ✓

WATER TANK:

GROUND: X

OVERHEAD: ✓

WATER TANK CAPACITY: 1000 Lts.

Remarks If any: \* Overhead tank exists in campus.

\* No water supply to toilets.

\* Separate toilet exists for girls but needs roofing and doors.

\* Urinals need roofing

Sign of Head Master

Sign of School Mgt Committee

Sign of Surveyor

DINGAR HIGH SCHOOL  
DINGAR, KHURDA-752062  
NAME:Shyam Suan Sahoo  
NAME: 29.1.15Asim Kumar Jaiswal  
NAME: putruwh  
29/1/15Mr. Rahemat Ali  
29.1.15