

4

274

250

22/11/15

"स्वच्छ भारत अभियान"

DISTRICT: KHURDA      BLOCK: BEGUNIA      VILLAGE: BEGUNIA  
 SCHOOL NAME: GIRLS HS BEGUNIA      SCHOOL CODE: 21170401302  
 NO. OF STUDENT: 122      GIRLS: 122      BOYS: —  
 STATUS OF TOILET:      EXISTING: ✓      NOT EXISTING: —  
 TOILET REQUIREMENT:      GIRLS: NO      BOYS: NO  
 IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	✓ 1 NO.	
2	URINALS	3 NO'S	
3	DOORS(SIZE)	✓	To be replaced 5'x2.5'
4	FLOOR LEVEL	✓	
5	WALL LEVEL	✓	
6	INTERNAL PLASTER	✓	
7	OUTER PLASTER	✓	
8	INSPECTION CHAMBER	✓	Required to be repaired
9	LEASE PIT/ SEPTIC TANK ✓	✓	

SOURCE OF WATER: <sup>OPEN</sup> WELL WITH GREEL      BORE WELL WITH PUMP: X      HAND PUMP: ✓  
 WATER TANK: ✓      GROUND: X      OVERHEAD: ✓  
 WATER TANK CAPACITY: 1000 L.

Remarks If any: \* water connection with overhead tank required.  
 \* roof of asbestos in bad condition

*muly*  
 22-01-15  
 Sign of School Head Master  
 Minata Mohanty  
 NAME:  
 HEADMISTRESS  
 Girls' High School  
 BEGUNIA

*Saranga Kumar Reshmi Singh*  
 Sign of School Mgt Committee  
 Chairman, S.M.C  
 Girls' High School  
 Begunia, Khordha  
 NAME:

*Arjun K. Pariswal*  
 Sign of Surveyor  
 NAME: Arjun K. Pariswal  
 21/11/15