

295

25/1/15

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA

BLOCK: BEUNIA

VILLAGE: GODA

SCHOOL NAME: GODA PS

SCHOOL CODE: 211704083501

NO. OF STUDENT: 114

GIRLS: 58

BOYS: 56

STATUS OF TOILET:

EXISTING: ✓

NOT EXISTING: —

TOILET REQUIREMENT:

GIRLS: 1

BOYS: 1

IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	—	—
2	URINALS	—	—
3	DOORS(SIZE)	—	—
4	FLOOR LEVEL	—	—
5	WALL LEVEL	—	—
6	INTERNAL PLASTER	—	—
7	OUTER PLASTER	—	—
8	INSPECTION CHAMBER	—	—
9	LEASE PIT/ SEPTIC TANK	—	—

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: ✓

WATER TANK:

GROUND: X

OVERHEAD: X

WATER TANK CAPACITY:

Remarks If any:

* Existing toilet fully damaged

* New urinals and toilets need to be constructed with

bu facilities.

Signature
Sign of School Headmaster
Goda Prj. School
Goda, Khurda-752062
NAME: Janmejaya Sahoo

Sign of School Mgt Committee

absent member
NAME: जानमेया शहू

Sign of Surveyor

Signature
NAME: P. K. Prasad
Aom K. Prasad