

299

23/1/15

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA      BLOCK: BEGUNIA      VILLAGE: GODIPOKHARI  
 SCHOOL NAME: GODIPOKHARI PS      SCHOOL CODE: 2110410901  
 NO. OF STUDENT: 28      GIRLS: 12      BOYS: 16  
 STATUS OF TOILET:      EXISTING:       NOT EXISTING:   
 TOILET REQUIREMENT:      GIRLS: 1      BOYS: 1  
 If EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	—	—
2	URINALS	—	—
3	DOORS(SIZE)	—	—
4	FLOOR LEVEL	—	—
5	WALL LEVEL	—	—
6	INTERNAL PLASTER	—	—
7	OUTER PLASTER	—	—
8	INSPECTION CHAMBER	—	—
9	LEASE PIT/ SEPTIC TANK	—	—

SOURCE OF WATER:      BORE WELL WITH PUMP:       HAND PUMP:  Damaged  
 WATER TANK:      GROUND:       OVERHEAD:   
 WATER TANK CAPACITY:

Remarks if any: \* Two handpumps exists but non-functioning  
 \* Toilet exists but fully damaged  
 \* New toilets & urinals required  
 \* Power supply absent

Sign of School Head Master  
Baiku Nathi School  
 NAME:

Sign of School Mgt Committee  
 NAME: संजय सिन्हा

Sign of Surveyor  
Amr K. Patwal  
 NAME: Amr K. Patwal  
 23/1/15

23-1-015

9/1/15