

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA

BLOCK: BEAUNIA

VILLAGE: GOLAPATNA

SCHOOL NAME: GOLAPATNA PS

SCHOOL CODE: 21170401601

NO. OF STUDENT: 34

GIRLS: 14

BOYS: 20

STATUS OF TOILET:

EXISTING: ✓

NOT EXISTING: —

TOILET REQUIREMENT:

GIRLS: 1

BOYS: 1

IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	1	—
2	URINALS	—	2 No's need to be renovated
3	DOORS(SIZE)	—	3rd NO's need to be changed 6'x2.5'
4	FLOOR LEVEL	—	Needs flooring
5	WALL LEVEL	✓	—
6	INTERNAL PLASTER	X	Plastering Required
7	OUTER PLASTER	X	Plastering Required
8	INSPECTION CHAMBER	X	
9	LEASE PIT/ SEPTIC TANK	✓	Damaged.

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: ✓

WATER TANK:

GROUND: X

OVERHEAD: X

WATER TANK CAPACITY:

Remarks if any: * water supply with overhead tank required to toilets.

Signature of School Head Master
29/1/2015

Signature of School Mgt Committee
29.1.2015

Signature of Surveyor
29/1/15
Name: Anuraj Kumar Jaiswal

NAME: Bejoya Kumar
M. Jaiswal

NAME: ଅଧ୍ୟକ୍ଷ
ବିଦ୍ୟାଳୟ ପରିଚାଳନା କମିଟି
ଗୋଲାପାଟଣା ପ୍ରାଥମିକ ବିଦ୍ୟାଳୟ