

“स्वच्छ भारत अभियान”

DISTRICT: KHURDA                      BLOCK: BEGUNIA                      VILLAGE: BEGUNIA

SCHOOL NAME: GOPABANDHU HS                      SCHOOL CODE: 21170401304

NO. OF STUDENT: 400                      GIRLS: 150                      BOYS: 250

STATUS OF TOILET:                      EXISTING: ✓                      NOT EXISTING: —

TOILET REQUIREMENT:                      GIRLS: X                      BOYS: 1

IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	1 NO.	1 damaged
2	URINALS	2 NOS	
3	DOORS(SIZE)	✓	
4	FLOOR LEVEL	✓	—
5	WALL LEVEL	✓	—
6	INTERNAL PLASTER	✓	—
7	OUTER PLASTER	✓	
8	INSPECTION CHAMBER	X	
9	LEASE PIT/ SEPTIC TANK ✓	✓	

SOURCE OF WATER:                      BORE WELL WITH PUMP: ✓                      HAND PUMP: ✓

WATER TANK: X                      GROUND: X                      OVERHEAD: X

WATER TANK CAPACITY:

Remarks If any: \* septic tank condition not good  
 \* urinals roof open  
 \* water supply to toilet with overhead tank required.

22/1/15  
 Sign of HEADMASTER  
 Gopabandhu High School  
 Begunia, Khordha  
 NAME: Bharat Jais

सुरेश पोद्दार  
 Sign of School Mgt Committee  
 Chairperson  
 SMC  
 Gopabandhu High School, Begunia  
 Khordha  
 सुरेश पोद्दार  
 22.1.2015

Sign of Surveyor  
 NAME: P. K. Patel  
 Arun C. Patilwal  
 22/1/15