

29/1/15

314

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA

BLOCK: BEGUNIA

VILLAGE: KOTALANGA

SCHOOL NAME: JAGANNATH VIHAR PROJECT P.S.

SCHOOL CODE: 21170413902

NO. OF STUDENT: 12

GIRLS: 6

BOYS: 6

STATUS OF TOILET:

EXISTING: ✓

NOT EXISTING: —

TOILET REQUIREMENT:

GIRLS:

BOYS:

IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	—	Need to be replaced
2	URINALS	—	2 in No's, Needs repairing
3	DOORS(SIZE)	—	3 in No's, size small 6x2's
4	FLOOR LEVEL	X	Needs flooring
5	WALL LEVEL	✓	—
6	INTERNAL PLASTER	✓	—
7	OUTER PLASTER	✓	—
8	INSPECTION CHAMBER	X	—
9	LEASE PIT/ SEPTIC TANK	✓	B —

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: ✓

(Needs Repairing)

WATER TANK:


GROUND: X

OVERHEAD: X


WATER TANK CAPACITY:

Remarks If any:

\* Overhead tank with water supply to toilets required.  
\* Roofing of urinals required

  
Sign of School Head Master 29-1-15  
headmaster  
J.V.P. Pny. School  
Uttareswar, Kotalanga  
NAME: Bikram Chhapra

Sign of School Mgt Committee  
No Committee  
NAME:

  
Sign of Surveyor 29/1/15  
Arjun Kumar Jaiswal  
NAME: P. K. Boudh