

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA BLOCK: BEAONIA VILLAGE: JALAVAR
SCHOOL NAME: JALAVAR UAUPS SCHOOL CODE: 21170408101
NO. OF STUDENT: 134 GIRLS: 71 BOYS: 63
STATUS OF TOILET: EXISTING: ✓ NOT EXISTING: -
TOILET REQUIREMENT: GIRLS: 2 BOYS: 1
IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	-	1 No. Need to be replaced
2	URINALS	2 in No's	-
3	DOORS(SIZE)	✓	-
4	FLOOR LEVEL	-	Flooring needs to be changed
5	WALL LEVEL	✓	-
6	INTERNAL PLASTER	✓	-
7	OUTER PLASTER	✓	-
8	INSPECTION CHAMBER	X	-
9	LEASE PIT/ SEPTIC TANK	✓	Damaged

SOURCE OF WATER: Well BORE WELL WITH PUMP: X HAND PUMP: ✓
WATER TANK: GROUND: OVERHEAD: ✓ (without any connect'ion)

WATER TANK CAPACITY: 500 LR.
Remarks If any: * Water supply to the toilets required
* Septic tank needs to be repaired

Signature
Sign of School Head Master

Kartik mangangj
Sign of School Mgt Committee

Signature
Sign of Surveyor
Arun Kumar Patra
NAME: P. K. Patra

NAME: Signature NAME: