



336

25/11/15

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA

BLOCK: BEAVNIA

VILLAGE: PARICHHALA

SCHOOL NAME: JAMUSAHU P U P S

SCHOOL CODE: 2117040 & 001

NO. OF STUDENT: 62

GIRLS: 22

BOYS: 40

STATUS OF TOILET:

EXISTING: ✓

NOT EXISTING: —

TOILET REQUIREMENT:

GIRLS: 1

BOYS: 1

If EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	—	—
2	URINALS	—	—
3	DOORS(SIZE)	—	—
4	FLOOR LEVEL	—	—
5	WALL LEVEL	—	—
6	INTERNAL PLASTER	—	—
7	OUTER PLASTER	—	—
8	INSPECTION CHAMBER	—	—
9	LEASE PIT/ SEPTIC TANK	—	—

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: ✓

WATER TANK:

GROUND: X

OVERHEAD: X

WATER TANK CAPACITY:

Remarks if any: * Existing toilet fully damaged, new construction of toilets and urinals to be constructed with full facilities.

Jagabandhu Panda.

Sign of School Head Master
Headmaster

Jamusahi P.U.P. School

NAME:

Sign of School Mgt Committee

absent

NAME:

Panda.

Sign of Surveyor

NAME:

Arun K. Jaiswal