

BT

339

24/1/15

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA      BLOCK: BEWUNIA      VILLAGE: ROUTAPADA  
 SCHOOL NAME: JHARMUNDA PS      SCHOOL CODE: 21170414001  
 NO. OF STUDENT: 26      GIRLS: 13      BOYS: 13  
 STATUS OF TOILET:      EXISTING:       NOT EXISTING:   
 TOILET REQUIREMENT:      GIRLS: 1      BOYS: X  
 IF EXISTING:

| SI.NO. | ITEM                   | CONDITION    |                                    |
|--------|------------------------|--------------|------------------------------------|
|        |                        | GOOD IN NOS. | TO BE REPLACED IN NOS.             |
| 1      | WC                     | ✓ 1 NO.      | —                                  |
| 2      | URINALS                | 2 in NO.     | —                                  |
| 3      | DOORS(SIZE)            | 3 in NO.     | 1 door of size 6'x2' to be changed |
| 4      | FLOOR LEVEL            | ✓            | —                                  |
| 5      | WALL LEVEL             | ✓            | —                                  |
| 6      | INTERNAL PLASTER       | ✓            | —                                  |
| 7      | OUTER PLASTER          | ✓            | —                                  |
| 8      | INSPECTION CHAMBER     | X            | —                                  |
| 9      | LEASE PIT/ SEPTIC TANK | ✓            | —                                  |

SOURCE OF WATER:      BORE WELL WITH PUMP:       HAND PUMP:  (not useful for drinking)  
WATER TANK:      GROUND:       OVERHEAD:

WATER TANK CAPACITY:  
 Remarks If any: \* Roof required over urinals. One urinal need to be constructed  
 \* Overhead tank with water supply to the toilets required  
 \* No electricity

Signature of School Head Master  
 NAME: Samaranjan Samantaray

Sign of School Mgt Committee  
 NAME: Bhusant Kumar Mahapatra

Signature of Surveyor  
 NAME: P. K. Parwal  
 Date: 24/1/15