

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA BLOCK: BEGUNIA VILLAGE: HAJA
SCHOOL NAME: KALACHUAPATANA PS SCHOOL CODE: 21170407201
NO. OF STUDENT: 40 GIRLS: 20 BOYS: 20
STATUS OF TOILET: EXISTING: ✓ NOT EXISTING: —
TOILET REQUIREMENT: GIRLS: 1 BOYS: 1
IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	—	2 No.' to be replaced
2	URINALS	—	2 No. to be repaired.
3	DOORS(SIZE)	—	to be replaced 6'x 2.5'
4	FLOOR LEVEL	—	Flooring required
5	WALL LEVEL	✓	—
6	INTERNAL PLASTER	X	Plastering required
7	OUTER PLASTER	✓	
8	INSPECTION CHAMBER	X	
9	LEASE PIT/ SEPTIC TANK	✓	Damaged

SOURCE OF WATER: BORE WELL WITH PUMP: X HAND PUMP: ✓
WATER TANK: GROUND: X OVERHEAD: X
WATER TANK CAPACITY:

Remarks If any: * Overhead tank with water supply required.
 * Roofing of urinals required.

[Signature]
 Sign of School Head Master

[Signature]
 Sign of School Mgt Committee

[Signature]
 Sign of Surveyor
 26/11/15
 Arun Kumar Patra

NAME: Prakash Chand Nayak

NAME: Mahanta Nayak

NAME: I. K. Patra

CHUDHARIAN'S & Co.
 108, Bhubaneswar, Orissa
 751001