

"स्वच्छ भारत अभियान"

DISTRICT: KHORDA

BLOCK: BEGUNIA

VILLAGE: BASUDEVPUR

SCHOOL NAME: KANPUR P.S

SCHOOL CODE: 21170408502

NO. OF STUDENT: 107

GIRLS: 65

BOYS: 42

STATUS OF TOILET:

EXISTING: ✓

NOT EXISTING: —

TOILET REQUIREMENT:

GIRLS: 1

BOYS: X

IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	X <del>NO.</del>	1 No. in damaged condition.
2	URINALS	X	—
3	DOORS(SIZE)	X	—
4	FLOOR LEVEL	X	—
5	WALL LEVEL	NA	—
6	INTERNAL PLASTER	NA	—
7	OUTER PLASTER	UNA	—
8	INSPECTION CHAMBER	X	—
9	LEASE PIT/ SEPTIC TANK	X	—

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: ✓

WATER TANK:

GROUND: X

OVERHEAD: X

WATER TANK CAPACITY: X

Remarks if any: \* urinal and toilet exist but upto 80% damaged

\* New construction required

\* No power supply inside school premises

Jagan Behari Belora

Sign of School Head Master

Sign of School Mgt Committee

Sign of Surveyor

22/1/2015

NAME: Jagan Behari Belora  
HEADMASTER  
KANPUR PRIMARY SCHOOL

NAME: 9910919088  
Chairperson  
Kanpur Primary School  
Yamuna Nayak

NAME: P. U. Prasad  
Arun K. Daswal