

29/11/15

309

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA

BLOCK: BEAUNIA

VILLAGE: KATHAKHUNTA

SCHOOL NAME: KATHAKHUNTA PS

SCHOOL CODE: 21170415101

NO. OF STUDENT: 57

GIRLS: 27

BOYS: 30

STATUS OF TOILET:

EXISTING: ✓

NOT EXISTING: —

TOILET REQUIREMENT:

GIRLS: 1

BOYS: 1

IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	—	1 Need to be replaced
2	URINALS	—	Needs full renovation
3	DOORS(SIZE)	✓	—
4	FLOOR LEVEL	X	—
5	WALL LEVEL	✓	—
6	INTERNAL PLASTER	X	Needs Plastering
7	OUTER PLASTER	✓	Needs Repair
8	INSPECTION CHAMBER	X	—
9	LEASE PIT/ SEPTIC TANK	✓	Needs Repair

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: ✓

WATER TANK:

GROUND: X

OVERHEAD: X

WATER TANK CAPACITY:

Remarks if any:

- \* Overhead tank with water supply to toilets required.
- \* Existing toilet needs full renovation

S. Sahoo

Sign of School Head Master

29.11.2015

**Signature**

NAME:

Shyam Sunder Sahoo

Komalini Bhojakata

Sign of School Mgt Committee

**CHAIR PERSON (S.M.C)**

Kathakhuntia Pny. School

NAME:

Sign of Surveyor

Asim Kumar Pansral

NAME:

P. U. Pansral