

27

311

23/1/15

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA

BLOCK: BEGUNIA

VILLAGE: KENDUPALLI

SCHOOL NAME: KENDUPALLI MALLIPADARAR K.CUP

SCHOOL CODE: 21170408801

NO. OF STUDENT: 51

GIRLS: 24

BOYS: 27

STATUS OF TOILET:

EXISTING: ✓

NOT EXISTING: —

TOILET REQUIREMENT:

GIRLS: 1

BOYS: 1

IF EXISTING:

| SI.NO. | ITEM | CONDITION | |
|--------|------------------------|--------------|------------------------|
| | | GOOD IN NOS. | TO BE REPLACED IN NOS. |
| 1 | WC | — | — |
| 2 | URINALS | — | — |
| 3 | DOORS(SIZE) | — | — |
| 4 | FLOOR LEVEL | — | — |
| 5 | WALL LEVEL | — | — |
| 6 | INTERNAL PLASTER | — | — |
| 7 | OUTER PLASTER | — | — |
| 8 | INSPECTION CHAMBER | — | — |
| 9 | LEASE PIT/ SEPTIC TANK | — | — |

SOURCE OF WATER: WELL

BORE WELL WITH PUMP: X

HAND PUMP: ✓

WATER TANK:

GROUND: X

OVERHEAD: X

WATER TANK CAPACITY:

Remarks if any:

- * Existing toilet locked and key lost due to damage
- * as per the statement of HM
- * Overhead tank with water supply required
- * Ladies toilet required

Nerupama Tripathy, 23.01.15
Sign of School Head Master

912 HEADMASTER
KENDUPALLI MALLIPADAR
KANHUCHARAN U.P (M.E) SCHOOL
AT-KENDUPALLI, KHORDHA

Sign of School Mgt Committee

Kailash Ch. Sircar

NAME: 23-1-15

CHAIRMAN S.M.C

Kendupalli Mallipadar Kanhucharan
U.P (M.E) School

Sign of Surveyor

23/1/15
NAME: P.K. Prasad

Anur K. Dasgupta