

28

310

28/11/15

"स्वच्छ भारत अभियान"

DISTRICT: KHRDHA

BLOCK: BEGUNIA

VILLAGE: KENDUPALLI

SCHOOL NAME: KENDUPALLI PS

SCHOOL CODE: 21170408802

NO. OF STUDENT: 87

GIRLS: 43

BOYS: 44

STATUS OF TOILET:

EXISTING: ✓

NOT EXISTING: —

TOILET REQUIREMENT:

GIRLS: ✗ 1

BOYS: ✗

If EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	1	—
2	URINALS	2	—
3	DOORS(SIZE)	✓	—
4	FLOOR LEVEL	✓	Flooring required
5	WALL LEVEL	✓	—
6	INTERNAL PLASTER	✓	—
7	OUTER PLASTER	✓	—
8	INSPECTION CHAMBER	✗	—
9	LEASE PIT/ SEPTIC TANK	✓	—

SOURCE OF WATER: WELL

BORE WELL WITH PUMP: ✗

HAND PUMP: ✓

WATER TANK:

GROUND: ✗

OVERHEAD: ✗

WATER TANK CAPACITY:

Remarks If any: * Tiling required for toilets and urinals.
 * Overhead tank required for water supply to toilets.
 * Water supply to be given.

Lingaraj Sethi
 Sign of School Head Master

HEADMASTER 28-11-15

Kendupalli Govt. Primary School

NAME:

Sign of School Mgt Committee

S.M.C. CHAIRPERSON P.P.S

Kendupalli Govt. Primary School

NAME:

Sign of Surveyor

NAME: P. K. P. S. 28/11/15

Arjun K. Sankar