

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA BLOCK: BEGUNIA

VILLAGE: KHADIPADAR

SCHOOL NAME: KHADIPADAR PS

SCHOOL CODE: 21170416001

NO. OF STUDENT: 84

GIRLS: 33

BOYS: 51

STATUS OF TOILET:

EXISTING: ✓

NOT EXISTING: —

TOILET REQUIREMENT:

GIRLS: 1

BOYS: 1

IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	/	/
2	URINALS		
3	DOORS(SIZE)		
4	FLOOR LEVEL		
5	WALL LEVEL		
6	INTERNAL PLASTER		
7	OUTER PLASTER		
8	INSPECTION CHAMBER		
9	LEASE PIT/ SEPTIC TANK		

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: ✓

WATER TANK:

GROUND: X

OVERHEAD: X

WATER TANK CAPACITY:

Remarks if any:

- \* Existing toilet fully damaged
- \* Full facilities toilets & urinals required
- \* No power supply

Sattanak  
 Sign of School Head Master  
 Head Master  
 Khadipadar Pry. School  
 NAME: Dist. Khurda

M. Harit Raut  
 Sign of School Mgt Committee  
 Khadipadar Pry. School  
 NAME:

Arjun Jaiswal  
 Sign of Surveyor  
 Arjun Kumar Jaiswal  
 NAME: P. K. Pruthi

Sandhyaarani Pattanaiik.