

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA

BLOCK: BEAUNIA

VILLAGE: KOKASINGH

SCHOOL NAME: KOKASINGH PS

SCHOOL CODE: 21170410002

NO. OF STUDENT: 43

GIRLS: 27

BOYS: 16

STATUS OF TOILET:

EXISTING: ✓

NOT EXISTING: —

TOILET REQUIREMENT:

GIRLS: 1

BOYS: 1

IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	1 in No.	—
2	URINALS	1 in No.	—
3	DOORS(SIZE)	✓	—
4	FLOOR LEVEL	✓	Flooring needs repair
5	WALL LEVEL	✓	—
6	INTERNAL PLASTER	✓	—
7	OUTER PLASTER	✓	—
8	INSPECTION CHAMBER	X	—
9	LEAK PIT/ SEPTIC TANK	✓	Damaged, needs repair

SOURCE OF WATER: Well

BORE WELL WITH PUMP: X

HAND PUMP: ✓ (Needs repair)

WATER TANK:

GROUND: X

OVERHEAD: ✓

WATER TANK CAPACITY: 1000 Ltr.

Remarks If any: * Overhead tank with water supply to toilets required

G. Sahoo
Sign of School Head Master

HEADMASTER

NAME: Gouranga Sahoo

Sign of School Mgt Committee

NAME: Suresa Behera

Arun
29/11/15
Sign of Surveyor

Arun Kumar Das

NAME: P. K. Bhowmik