

315

23/1/15

"स्वच्छ भारत अभियान"

DISTRICT: KHANDHA BLOCK: BEGUNIA VILLAGE: KOTAPALA
 SCHOOL NAME: KOTAPALLA BARASAHI CPS SCHOOL CODE: 21170411801
 NO. OF STUDENT: 97 GIRLS: 55 BOYS: 42
 STATUS OF TOILET: EXISTING: NOT EXISTING:
 TOILET REQUIREMENT: GIRLS: 1 BOYS: X
 If EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	1 No.	—
2	URINALS	2 in NO.	Damaged, Need to be repaired
3	DOORS(SIZE)	3	Need to be replaced 6'x2.5'
4	FLOOR LEVEL	✓	Needs to be repaired
5	WALL LEVEL	—	Need to be tiled
6	INTERNAL PLASTER	✓	—
7	OUTER PLASTER	✓	—
8	INSPECTION CHAMBER	X	—
9	LEASE PIT/ SEPTIC TANK	X	Damaged, Need to be constructed

SOURCE OF WATER: ~~Tube Well~~ BORE WELL WITH PUMP: X HAND PUMP:

WATER TANK: GROUND: X OVERHEAD: X

WATER TANK CAPACITY:

Remarks if any: * Overhead tank with water supply required
 * Flooring and tiling required

Sign: *[Signature]*
 Head Master
 Kotapalla Barasahi
 Centre Pny. School
 NAME: *[Name]*

[Signature]
 Sign of School Mgt Committee 23/1/15
 CHAIRMAN, S.M.C.
 Kotapalla Barasahi Centre
 Primary School
 A/P.O. Kotapalla, Dist-Khurda

[Signature]
 Sign of Surveyor
 NAME: *[Name]*
 23/1/15
 Anurag Prasad