

29/11/15

347

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHA

BLOCK: BEGUNIA

VILLAGE: SIMOR

SCHOOL NAME: KUNJBIHARI DEV UPS

SCHOOL CODE: 21170416602

NO. OF STUDENT: 85

GIRLS: 43

BOYS: 42

STATUS OF TOILET:

EXISTING: ✓

NOT EXISTING: —

TOILET REQUIREMENT:

GIRLS: 1

BOYS: 1

IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	—	1 Need to be replaced
2	URINALS	3 in Nos	2 2 No. Needs flooring & Roofing
3	DOORS(SIZE)	✓	—
4	FLOOR LEVEL	✓	—
5	WALL LEVEL	✓	—
6	INTERNAL PLASTER	✓	—
7	OUTER PLASTER	✓	—
8	INSPECTION CHAMBER	✓	—
9	LEASE PIT/ SEPTIC TANK	✓	—

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: ✓

WATER TANK:

GROUND: X

OVERHEAD: X

WATER TANK CAPACITY:

Remarks if any:

* Overhead tank with water supply to the toilets required.
* urinals and toilets for boys required separately

Sign of School Head Master
K.B. Dev U.P.(M.E.) School
Simore, Khurda
NAME: SABITA MANJARI
BEHERA

Sumati Pradhan
CHA of School Water Committee
K.B. Dev U.P.(M.E.) School
Simore, Khordha
NAME: SUMATI PRADHAN

Sign of Surveyor
NAME: Anam Kumar Patil wal
29/11/15