

"स्वच्छ भारत अभियान"

DISTRICT: KHORDHABLOCK: BEGUNIAVILLAGE: KUNJURISCHOOL NAME: KUNJURI CPSSCHOOL CODE: 21170410201NO. OF STUDENT: 48GIRLS: 17BOYS: 31

STATUS OF TOILET:

EXISTING: NOT EXISTING: 

TOILET REQUIREMENT:

GIRLS: 1BOYS: 1

If EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	—	1 No. needs to be changed
2	URINALS	—	Needs renovation
3	DOORS(SIZE)	—	Needs replaced 2 in No. 6'x2'5"
4	FLOOR LEVEL	✓	—
5	WALL LEVEL	X	✓
6	INTERNAL PLASTER	X	Roof needs plastering
7	OUTER PLASTER	X	Needs plastering
8	INSPECTION CHAMBER	X	—
9	LEASE PIT/ SEPTIC TANK	✓	Damaged

SOURCE OF WATER:

BORE WELL WITH PUMP: HAND PUMP:  1 + 1


WATER TANK:

GROUND: OVERHEAD: 

(1 needs repairing)


WATER TANK CAPACITY: 1000 Ltr.

Remarks If any: \* Roofing of the urinals required  
\* Water supply with overhead tank to toilets required

  
Sign of School Head Master  
**Headmaster**  
Kunjuri Pry. School  
NAME:

Ashish Nayak  
29.1.2015

SARADINE GURU  
Sign of School Mgt Committee  
**CHAIRMAN S.M.C**  
**KUNJURI PRY SCHOOL**  
NAME: **KHURDA**

  
29/1/15  
Sign of Surveyor  
**Anam Kumar**  
NAME: K. U. Prasad