



317

28/1/15

“स्वच्छ भारत अभियान”

DISTRICT: KHORDHA

BLOCK: BEAUNIA

VILLAGE: KURADHILO

SCHOOL NAME: KURADHILO UPS

SCHOOL CODE: 21170411001

NO. OF STUDENT: 171

GIRLS: 60

BOYS: 111

STATUS OF TOILET:

EXISTING: ✓

NOT EXISTING: —

TOILET REQUIREMENT:

GIRLS: 1

BOYS: 1

IF EXISTING:

SI.NO.	ITEM	CONDITION	
		GOOD IN NOS.	TO BE REPLACED IN NOS.
1	WC	1	Damaged to be repaired
2	URINALS	2 in No.	Damaged, to be replaced
3	DOORS(SIZE)	3 in No.	—
4	FLOOR LEVEL	✓	Flooring Required in urinal
5	WALL LEVEL	—	—
6	INTERNAL PLASTER	✓	—
7	OUTER PLASTER	✓	—
8	INSPECTION CHAMBER	X	—
9	LEASE PIT/ SEPTIC TANK	X	—

SOURCE OF WATER:

BORE WELL WITH PUMP: X

HAND PUMP: ✓ Damaged

WATER TANK:

GROUND: X

OVERHEAD: X

WATER TANK CAPACITY:

Remarks if any:

- \* Overhead tank required with supply
- \* Flooring required
- \* No power supply

Gangadhar Behera  
Sign of School Head Master

Sign of School Mgt Committee

Sign of Surveyor

Kuradhilo Project U P School

NAME: G. Gangadhar Behera

NAME: Gangadhar Behera

NAME: P. Parkwal

ଶ୍ରୀମତୀ କୁମାରୀ ଚାନ୍ଦିଆ

Arunde. Parkwal